Bridge Inspection Report

02202 SH 367 White Co. over LITTLE RED RIVER



Inspection Date:

Inspected By:

Inspection Type(s):


TABLE OF CONTENTS

	PAGE NUMBER
LOCATION MAP	3
NATIONAL BRIDGE INVENTORY	8
ELEMENTS	9
PICTURES	11
SKETCHES	12

Inspection Date: Facility Carried: SH 367 White Co.

Bridge Inspection Report


Location Map



Inspection Date: Facility Carried: SH 367 White Co.

Bridge Inspection Report


Location Map



Inspection Date: Facility Carried: SH 367 White Co.

Bridge Inspection Report


Location Map



Inspection Date: Facility Carried: SH 367 White Co.

Bridge Inspection Report

Location Map



nspector:	Structure Number:	02202

Inspection Date: Facility Carried: SH 367 White Co.

Bridge Inspection Report

Executive Summary

Log Mile looking Northeast

Inspection Date: Facility Carried: SH 367 White Co.

Bridge Inspection Report

National Bridge Inventory

(97) YEAR OF IMPROVEMENT COST ESTIMATE

(115) YEAR OF FUTURE ADT 2028

(114) FUTURE ADT 10435

National Bridge Inventory	
IDENTIFICATION	INSPECTIONS
(1) STATE CODE 056 - Arkansas	(90) INSPECTION DATE 05/23/2016
(8) STRUCTURE NUMBER 02202	(91) DESIGNATED INSPECTION FREQUENCY 24
(5) INV. ROUTE (ON/UNDER) 1 3 1 367 0	(92) CRITICAL FEATURE INSPECTION (93) CFI DATE
(2) HIGHWAY AGENCY 05 (3) COUNTY CODE 145	A. FRACTURE CRITICAL DETAIL Y 24 05/10/2017
(4) PLACE CODE 60780	B. UNDERWATER INSPECTION N
(6) FEATURES INTERSECTED LITTLE RED RIVER	C. OTHER SPECIAL N
(7) FACILITY CARRIED SH 367 White Co.	CONDITION
(9) LOCATION .3 M N OF SH 36	(58) DECK 6
(11) MILEPOINT 0.470 (12) BASE HIGHWAY NETWORK 0	(59) SUPERSTRUCTURE 5 (60) SUBSTRUCTURE 6
(13A) LRS INVENTORY ROUTE 0000000000 (13B) SUBROUTE NUMBER 0	(61) CHANNEL & CHANNEL PROTECTION 7 (62) CULVERT N
(16) LATITUDE 35.25489 (17) LONGITUDE -91.67633	LOAD RATING AND POSTING
(98A) BORDER BRIDGE CODE	(31) DESIGN LOAD 4
PERCENT RESPONSIBILITY (99) BORDER BRIDGE STRUCT	(63) METHOD USED TO DETERMINE OPERATING RATING 1
STRUCTURE TYPE AND MATERIAL	(64) OPERATING RATING 43.0
(43) STRUCTURE TYPE, MAIN	(65) METHOD USED TO DETERMINE INVENTORY RATING 1
A) KIND OF MATERIAL/DESIGN: 4 - Steel continuous	(66) INVENTORY RATING 26.0
B) TYPE OF DESIGN/CONSTR: 03 - Girder and Floorbeam System	(70) BRIDGE POSTING 5
(44) STRUCTURE TYPE, APPROACH SPANS	(41) STRUCTURE OPEN/POSTED/CLOSED A
A) KIND OF MATERIAL/DESIGN: 0 - Other	APPRAISAL
B) TYPE OF DESIGN/CONSTR: 00 - Other	(67) STRUCTURAL EVALUATION 5
(45) NUMBER OF SPANS IN MAIN 5 (46) NUMBER OF APPROACH 0	(68) DECK GEOMETRY 4
(107) DECK STRUCTURE TYPE 1 (108A) WEARING SURFACE 1 (108B) DECK MEMBRANE 0 (108C) DECK PROTECTION 0	(69) UNDERCLEARANCES, VERTICAL & HORIZONTAL N
AGE OF SERVICE	(71) WATERWAY ADEQUACY 7
(27) YEAR BUILT 1949 (106) YEAR RECONSTRUCTED 0000	(72) APPROACH ROADWAY ALIGNMENT 7
(42) TYPE OF SERVICE ON 1 UNDER 5	(36) TRAFFIC SAFETY FEATURE 36A) BRIDGE RAILINGS: 0
(28) LANES ON 02 UNDER 00	36B) TRANSITIONS: 0
(29) AVERAGE DAILY TRAFFIC 6800 (19) BYPASS DETOUR LENGTH	
(30) YEAR OF AVERAGE DAILY TRAFFIC 2014	36D) APPROACH GUARDRAIL ENDS: 0
(109) AVERAGE DAILY TRUCK TRAFFIC 1	(113) SCOUR CRITICAL BRIDGES 5
GEOMETRIC DATA	SUFFICIENCY RATING 0 STATUS 58.8
(48) LENGTH OF MAX SPAN (ft.) 100 (49) STRUCTURE LENGTH (ft.) 414	CLASSIFICATION
(50) CURB/SIDEWALK WIDTHS (ft.) LEFT 1.5 RIGHT 1.5	(112) NBIS BRIDGE LENGTH Y
(51) BRDG RDWY WIDTH CURB-TO-CURB (ft.) 27.9	(104) HIGHWAY SYSTEM OF THE INVENTORY ROUTE 0
(52) DECK WIDTH, OUT-TO-OUT (ft.) 31.8	(26) FUNCTIONAL CLASSIFICATION OF INVENTORY ROUTE 07
(32) APPROACH ROADWAY WIDTH (ft.) 42.0	(100) STRAHNET HIGHWAY DESIGNATION 0
(33) BRIDGE MEDIAN 0 (34) SKEW (DEG.) 0	(101) PARALLEL STRUCTURE DESIGNATION N
(35) STRUCTURE FLARED 0 (10) INV RTE, MIN VERT CLEAR (ft.) 99.99	(102) DIRECTION OF TRAFFIC 2
(47) TOTAL HORIZONTAL CLEARANCE (ft.) 30.8 (53) VERTICAL CLEARANCE OVER BRIDGE ROADWAY (ft.) 99.99	(103) TEMP STRUCTURE
(54) VERTICAL CLEARANCE OVER BRIDGE ROADWAY (II.) 99.99 (54) VERTICAL UNDER CLEARANCE (ft.) N 0	(105) FEDERAL LANDS HIGHWAYS 0
(55) LATERAL UNDER CLEARANCE RIGHT (ft.) N 99.9	(110) DESIGNATED NATIONAL NETWORK 0
	(20) TOLL 3
(56) MIN LATERAL UNDER CLEARANCE (ft.) 0	(21) MAINTENANCE RESPONSIBILITY 01
(56) MIN LATERAL UNDER CLEARANCE (ft.) 0 PROPOSED IMPROVEMENTS	(21) MAINTENANCE RESPONSIBILITY 01 (22) OWNER 01
(56) MIN LATERAL UNDER CLEARANCE (ft.) 0 PROPOSED IMPROVEMENTS (75A) TYPE OF WORK PROPOSED (75B) WORK DONE BY	(21) MAINTENANCE RESPONSIBILITY 01 (22) OWNER 01 (37) HISTORICAL 5
(56) MIN LATERAL UNDER CLEARANCE (ft.) 0 PROPOSED IMPROVEMENTS (75A) TYPE OF WORK PROPOSED (75B) WORK DONE BY (76) LENGTH OF STRUCTURE IMPROVEMENT (ft.) 0	(21) MAINTENANCE RESPONSIBILITY 01 (22) OWNER 01 (37) HISTORICAL 5 NAVIGATION DATA
(56) MIN LATERAL UNDER CLEARANCE (ft.) 0 PROPOSED IMPROVEMENTS (75A) TYPE OF WORK PROPOSED (75B) WORK DONE BY (76) LENGTH OF STRUCTURE IMPROVEMENT (ft.) 0 (94) BRIDGE IMPROVEMENT COST (\$) 0	(21) MAINTENANCE RESPONSIBILITY 01 (22) OWNER 01 (37) HISTORICAL 5 NAVIGATION DATA (38) NAVIGATION CONTROL 0
(56) MIN LATERAL UNDER CLEARANCE (ft.) 0 PROPOSED IMPROVEMENTS (75A) TYPE OF WORK PROPOSED (75B) WORK DONE BY (76) LENGTH OF STRUCTURE IMPROVEMENT (ft.) 0	(21) MAINTENANCE RESPONSIBILITY 01 (22) OWNER 01 (37) HISTORICAL 5 NAVIGATION DATA

(116) MIN NAVIGATION VERT CLEARANCE, VERT LIFT BRIDGE (ft.) 0

(40) NAV HORIZONTAL CLEARANCE (ft.) 0

Inspection Date: Facility Carried: SH 367 White Co.

Bridge Inspection Report

Element Inspection

	Environment	Total Quantity	Units	Condition State 1	Condition State 2	Condition State 3	Condition State 4
12 - Reinforced Concrete Deck	1- Ben.	13165	sq. ft.	12283	255	627	0
	Deck crackir the entire wid SEE FORM Partial A/C o	dth of road	dway.		8" extendir	ng in some	cases
1080 - Delamination/Spall/Patched Area		69				69	
1090 - Exposed Rebar		32			32		
1130 - Cracking (RC and Other)		781			223	558	
510 - Wearing Surfaces		744	sq. ft.	744			
107 - Steel Open Girder/Beam	1- Ben.	824	ft.	546	136	142	0
	Section loss Bottom Fland bottom Fland Left & Right SEE FORM	ge at 3A & ge at 5A have secti	3B Lef	t bottom &			
1000 - Corrosion		278			136	142	
515 - Steel Protective Coating		4670	sq. ft.	3210	0	665	795
3420 - Peeling/Bubbling/Cracking (Steel Protective Coatings)		130					130
3440 - Effectiveness (Steel Protective Coatings)		1330				665	665
113 - Steel Stringer	1- Ben.	412	ft.	333	65	14	0
	Moderate rust 8 Heavy rust 8 SEE FORM	section lo				A, 3A, 3B.	
1000 Camanian							
1000 - Corrosion		79			65	14	
515 - Steel Protective Coating	+	79 474	sq. ft.	0	65 0	14 457	17
		_	sq. ft.	0			17 17
515 - Steel Protective Coating		474	sq. ft.	0 418		457	
515 - Steel Protective Coating 3440 - Effectiveness (Steel Protective Coatings)		474 474 455 ge at rand eaned and et sheared ack to top I	ft. om loca painted d on Rig	418 ations has d. ght side of	0 0 old section	457 457 37 n loss pres	17 0
515 - Steel Protective Coating 3440 - Effectiveness (Steel Protective Coatings)	1- Ben. Bottom Flandhas been cle Span 3 - Riv Span 5 - Cra	474 474 455 ge at rand eaned and et sheared ack to top I	ft. om loca painted d on Rig	418 ations has d. ght side of	0 0 old section	457 457 37 n loss pres	17 0
515 - Steel Protective Coating 3440 - Effectiveness (Steel Protective Coatings) 152 - Steel Floor Beam	1- Ben. Bottom Flandhas been cle Span 3 - Riv Span 5 - Cra SEE FORM	474 474 455 ge at rand eaned and et sheared ick to top I	ft. om loca painted d on Rig	418 ations has d. ght side of	0 0 old section	457 457 37 n loss pres m 3.	17 0
515 - Steel Protective Coating 3440 - Effectiveness (Steel Protective Coatings) 152 - Steel Floor Beam 1000 - Corrosion	1- Ben. Bottom Flandhas been cle Span 3 - Riv Span 5 - Cra SEE FORM	474 474 455 ge at rand eaned and et sheared ack to top IIII 36	ft. om loca painted d on Rig	418 ations has d. ght side of	0 0 old section	457 457 37 n loss pres n 3.	17 0

Inspection Date: Facility Carried: SH 367 White Co.

Bridge Inspection Report

Element Inspection

161 - Steel Pin and Pin & Hanger Assembly or both		8	each	0	0	8	0
	Pack rust ex functioning of Approximate SEE FORM	due to inwa ely 1/8" sed	ard rota	tion of botl	n abutmen	ts.	were not
1000 - Corrosion		8				8	
515 - Steel Protective Coating		21	sq. ft.	0			21
205 - Reinforced Concrete Column	1- Ben.	8	each	4	3	1	0
	SEE FORM	III					
1080 - Delamination/Spall/Patched Area		1			1		
1090 - Exposed Rebar		2			2		
1130 - Cracking (RC and Other)		1				1	
215 - Reinforced Concrete Abutment	1- Ben.	74	ft.	70	0	4	0
	Abutment 1 Abutment 1 of Abutment SEE FORM	- Minor sp is separa	all with	heavy rust			
1080 - Delamination/Spall/Patched Area		4				4	
234 - Reinforced Concrete Pier Cap	1- Ben.	102	ft.	93	7	2	0
	SEE FORM	III				•	•
1080 - Delamination/Spall/Patched Area		2				2	
1090 - Exposed Rebar		7			7		
301 - Pourable Joint Seal	1- Ben.	445	ft.	0	0	0	445
	All poured jo	ints leak.			l		l
2340 - Seal Cracking		445					445
305 - Assembly Joint without Seal	1- Ben.	191	ft.	0	191	0	0
-	SEE FORM Some joints		sed fror	n Abutmer	nts rotated.		•
2370 - Metal Deterioration or Damage		191			191		
311 - Movable Bearing	1- Ben.	4	each	0	0	4	0
-	Rusting with SEE FORM		ction los	s to maso	nry plates	at Abutme	nts 1 & 2.
1000 - Corrosion		3				3	
1020 - Connection		1				1	
515 - Steel Protective Coating		7	sq. ft.	0		7	
313 - Fixed Bearing	1- Ben.	8	each	0	0	4	4
-	SEE FORM	Ш					
1000 - Corrosion		4				4	
1020 - Connection		4					4
515 - Steel Protective Coating		58	sq. ft.	0			58
330 - Metal Bridge Railing	1- Ben.	1656	ft.	0	1656	0	0
	Rust present	t on metal	railing.				
1000 - Corrosion	·	1656			1656		
515 - Steel Protective Coating		3776	sq. ft.	0		3776	

Inspection Date: Facility Carried: SH 367 White Co.

Bridge Inspection Report

Pictures

Inspection Date: Facility Carried: SH 367 White Co.

Bridge Inspection Report

Sketches

Inspection Date: Facility Carried: SH 367 White Co.

Bridge Inspection Report

Maintenance Needs

Date Reported: 05/28/2015 Priority: D - Routine

Work Code: Repair

Deficiency Description:

Rust with section loss to top Flange of Floor Beams.

Work Description:

Date Repairs Completed:

Maintenance Comments:

Stage: Open



PHOTO 1

Description

Rust with section loss to top flange of Floor beams.

Inspection Date: Facility Carried: SH 367 White Co.

Bridge Inspection Report

Maintenance Needs

Date Reported: 05/28/2015
Priority: D - Routine

Replace

Deficiency Description:

Sheared rivet at Floor Beam connection at Girder 2 at Span 3. 1st Floor Beam back from Pin & Hanger 3B.

Work Description:

Work Code:

Date Repairs Completed:

Maintenance Comments:

Stage: Open



PHOTO 1 De

Description

Sheared rivet at Floor beam connection at Girder #2 at Span #3. 1st floor beam back from 3B

Inspection Date: Facility Carried: SH 367 White Co.

Bridge Inspection Report

Maintenance Needs

Date Reported: 05/28/2015 Priority: D - Routine

Work Code: Repair

Deficiency Description:

Rust with section loss to bottom Flange of Stringer 1 at Span 4.

Work Description:

Date Repairs Completed:

Maintenance Comments:



PHOTO 1

Description

Span 4. Rust with section loss to top Flange of Floor Beam 3 & bottom of Stringer 1.

Inspection Date: Facility Carried: SH 367 White Co.

Bridge Inspection Report

Maintenance Needs

Date Reported: 05/10/2017

Priority: C - Important

Work Code: N/A

Deficiency Description:

Heavy rust with section loss to bottom Flange of Girders 1 and 2 at Pin & Hangers 1A, 3A, 3B, & 5A.

Work Description:

Date Repairs Completed:

Maintenance Comments:



PHOTO 1

Description

Heavy rust with section loss to bottom Flange of Girder 2 at Pin & Hanger 3A.

Stage: Assigned



PHOTO 2

Description

Heavy rust with section loss to bottom Flange of Girder 1 at Pin & Hanger 3B.

Inspection Date: Facility Carried: SH 367 White Co.

Bridge Inspection Report

Maintenance Needs

Date Reported: 05/28/2015 Priority: D - Routine

Work Code:

Deficiency Description:

Bearing 1 is sitting at the edge of Cap at Abutment 1.

Work Description:

Date Repairs Completed:

Maintenance Comments:



PHOTO 1

Description

Bearing 1 is sitting at the edge of Cap at Abutment 1.

Inspection Date: Facility Carried: SH 367 White Co.

Bridge Inspection Report

Maintenance Needs

Date Reported: 05/28/2015

Priority: C - Important

Work Code:

Deficiency Description:

Large, deep spall to Soffit with 12' of rebar exposed at Span 3.

Work Description:

Date Repairs Completed:

Maintenance Comments:



PHOTO 1

Description

Span 3. Spall 12' rebar exposed to Deck below.

Inspection Date: Facility Carried: SH 367 White Co.

Bridge Inspection Report

Maintenance Needs

Date Reported: 05/28/2015
Priority: C - Important

Work Code: Repair

Deficiency Description:

Rust with section loss and holes in Web of Stringer 1 at Spans 1 and 3.

Work Description:

Date Repairs Completed:

Maintenance Comments:



PHOTO 1

Description

Rust with section loss and holes in web of stringer #1 at Spans #1 and #3.

Inspection Date: Facility Carried: SH 367 White Co.

Bridge Inspection Report

Maintenance Needs

Date Reported: 05/10/2017

Priority: C - Important

Work Code: N/A

Deficiency Description:

Floor beam 1 has a crack in top Flange at Span 5.

Work Description:

Date Repairs Completed:

Maintenance Comments:

Stage: Assigned



PHOTO 1 Description

Floor beam 1 has a crack in top Flange at Span 5.



PHOTO 2

Description

Floor beam 1 has a crack in top Flange at Span 5.

Inspection Date: Facility Carried: SH 367 White Co.

Bridge Inspection Report

Maintenance Needs

Date Reported: 05/10/2017
Priority: C - Important

Work Code: N/A

Deficiency Description:

Pin & hangers have pack rust behind hangers. Pin & Hanger assemblies are not functioning due to inward rotation of both abutments.

Work Description:

Date Repairs Completed:

Maintenance Comments:



PHOTO 1

Description

Pack rust @ Pin & hanger assembly 1A @ Girder 1 Span 1.

Stage: Assigned



PHOTO 2

Description

Girder 2 Pin & Hanger assembly 5A. Pack Rust

Inspection Date: Facility Carried: SH 367 White Co.

Bridge Inspection Report

Maintenance Needs

Date Reported: 05/28/2015 Priority: D - Routine

Work Code:

Deficiency Description:

All poured joints are deteriorated & leak.

Work Description:

Date Repairs Completed:

Maintenance Comments:

Stage: Monitor



PHOTO 1

Description

All Poured Joints are deteriorated & leak.

Inspection Date: Facility Carried: SH 367 White Co.

Bridge Inspection Report

Maintenance Needs

Date Reported: 05/28/2015 Priority: D - Routine

Work Code:

Deficiency Description:

Unsealed cracks to Deck at all spans.

Spalls to Deck at most spans.

Work Description:

Date Repairs Completed:

Maintenance Comments:

Stage: Monitor



PHOTO 1

Description

Unsealed cracks to Deck at all spans.

Stage: Monitor



PHOTO 2

Description

Spalls to Deck at most spans.

Inspection Date: Facility Carried: SH 367 White Co.

Bridge Inspection Report

Maintenance Needs

Date Reported: 05/10/2017
Priority: C - Important

Work Code: N/A

Deficiency Description:

Cracked tack weld between bottom Flange & Gusset plate inside Girder 1 at end of Span 2. Cracked tack weld on outside of Girder 2 between bottom flange & cover plate @ end of Span 3.

Work Description:

Date Repairs Completed:

Maintenance Comments:

Stage: Open



PHOTO 1 Description

Cracked tack weld between bottom flange & gusset plate inside Girder #1 at end of Span #2.

Stage: Assigned



PHOTO 2

Description

Cracked tack weld on outside of Girder 2 between bottom flange & cover plate @ end of Span 3.

DIGT NO	STATE	PROJECT NO	FIBCA: YKAN	SHEET YO	I TOYAL SWEETS
6	ARK.	F-63(6)	1941	1	17

STATE OF ARKANSAS

STATE HIGHWAY COMMISSION

INDEX OF SHEETS

Sheet No	Owg No	Description
1	6165	Title Sheet
2	6169	Schedule of Grantities for Substructure.
3	6170	Loyout of Bridge over Little Red River-Br. No. 2202
4	6:71	Defails of Abutments-Br. No. 2202
5	6172	Details of Abutments-Br No. 2202
6	6173	Details of Piers-Br No. 2202
7	6/74	Details of Deck Plate Girder- 60' End Span
8	6175	Details of Deck Plate Girder-60-3' Center Span
9	6176	Petails of Deck Plate Girder-116-0" Canitlever Spans.
10	6:77	General Deiuls of Deck Plate Girder Spans
11	6/78	General Details of Deck Plate Girder Spans
12	6/79	Layout of Bridge over Little Red River Relief- Br. No. 2203.
13	5216	Details of Bent's for 36'0" I-Beam Spans.
14	52/7	Details of 36'-0" I-Beam Sparis
.5	1888	Embankment Construction of Br Ends and Backfill for Structures.
16	!391	Basis for Computing Excavation for Structures.
17	2387	Details of Project Markers, R/W Markers, and Bridge Name Piates.

PLAN OF PROPOSED BRIDGES

OVER LITTLE RED RIVER
SCARCY-JUDSONIAROAD
WHITE COUNTY


ROUTE 67 SEC. 13

JOB Nº 5233

FEDERAL AID DROJECT (YO.F-63(6)

QUANTITIES

ITEM NO	/TEM	QUANTITY UNIT
101	and the second s	0.73 Acre
103	Dry Excavation for Structures	er Su Ya
103	Wet Excavation for Structures	1330 u u
103	Solid Rock Excavations for Structures	52 n n
584808	Class "4" Concrete for Bridges	941.2 " "
SP#802	Class 5" Concrete for Bridges	810.6 , "
5.94 302	Seal Concrete for Bridges	380.8 a
SF# 803	Reinforcing Steel	240,150 6.63
SPA 201	14" Square Concrete Piling	1450 Lm Ft
3P4804	16" Octogo ol Concrete Piling	1965 , , ,
<i>805</i>	Concrete Ruiling	83C.5 " "
S.P&805	Concrete and Structural Steel Railing	822.5 * *
5P#807	Structural Steel in Beam Spans	, 663810 Lbs
810	Untreated Timber Piling	5304 Lin. Ft.
909	Riprop	330 Cu. Yd.
929	Bridge Name Plates-Type "A"	4 Each



CHAIRMAN Slote Highweil Commission

APPROVED

STATE MIGHWAY ENGINEEP
RECOMMENDED FOR APPROVAL.


DIATRICT ENGINEER
Fullic Roads Administration


APPROVED

COMMISSIONES
Foderal Works Agancy
Foderal Works Agancy

BRIDGES No. 2202 4 2203

DRAWING No. 6168








FEO. NOAC DIST. NO	STATE	FROJECT NO.	FISCAL YEAR	BHEET NG	AHEE CO
e	ARK.	F-G3(6)	194!	5	/7
STATE	JOB N	o. 5233			<u> </u>


BAR LIST FOR ABUTMENTS BENDING DIAGRAM MARK SIZE LENGTH 8-22 5-11" 6-52" 7-2" 3-0" 6-2" 16-11 6-10 7-10" 15-9 17-2" F38 40 9-9" 3-3" 10-3" F40 20 13-11 6-6 F41 20 5-11 7-5" 0-6 30-7' 28-7' 0-8" 1-84 9-1" YCTI-CTI 18-3" EV2 22-3" 17-3 18-3 13-3 __ A___ 14-6" 17-0" 14-9 16-9" H3, H15-H17, H22-H27, \$V3 12'-0" 14-0" 9*-3*" 11-3" 6-9" 1-3" 10-6" 1-8" 15-5 13-9" 15-10" 13-3" 9'-0" 7'-4" 10'-3' 12-0" 17'-1" 18-8" 11'-3" 40" 8-0" FG 3 0 7-8" Note: Dimensions relating to reinforcing are to centers of bars.

C5 1" 0 20-6" H2 \$ \$ 28'-7









GENERAL NOTES: For General Notes see Drwg. No. 6171

> SHEET NO. 2 DETAIL OF ABUTMENTS BRIDGE OVER LITTLE RED RIVER SEARCY -JUDSONIA ROAD WHITE COUNTY
> ROUTE 67 SEC. 13

ARKANSAS STATE HIGHWAY COMMISSION


LITTLE POCK. ARK.


Drawn By: MWH. Date: G-9-41


Traced By: MWH. Date: G-11-41

Scale: As noted


Checked By: Date:
BRIDGE NO. 2202 DRAWING NC. 6172

















CONTRACTOR CONTRACTOR

Bridge Inspection Report

02203
SH 367 WHITE
over
LITTLE RED RIVER RELIEF



Inspection Date:

Inspected By:

Inspection Type(s):


TABLE OF CONTENTS

	PAGE NUMBER
LOCATION MAP	3
NATIONAL BRIDGE INVENTORY	6
ELEMENTS	7
PICTURES	9
SKETCHES	10

Inspection Date: Facility Carried: SH 367 WHITE

Bridge Inspection Report

Location Map




Latitude: 35.25802 Longitude: -91.67386

Inspection Date: Facility Carried: SH 367 WHITE

Bridge Inspection Report

Location Map



Latitude: 35.25802 Longitude: -91.67386

Inspection Date: Facility Carried: SH 367 WHITE

Bridge Inspection Report

Executive Summary

Logmile looking North. Construction Job 5233.

Inspection Date: Facility Carried: SH 367 WHITE

Bridge Inspection Report

(96) TOTAL PROJECT COST

(114) FUTURE ADT 10435

(97) YEAR OF IMPROVEMENT COST ESTIMATE

(115) YEAR OF FUTURE ADT 2028

National Bridge Inventory	
IDENTIFICATION	INSPECTIONS
(1) STATE CODE 056 - Arkansas	(90) INSPECTION DATE 11/08/2016
(8) STRUCTURE NUMBER 02203	(91) DESIGNATED INSPECTION FREQUENCY 24
(5) INV. ROUTE (ON/UNDER) 1 3 1 367 0	(92) CRITICAL FEATURE INSPECTION (93) CFI DATE
(2) HIGHWAY AGENCY 05 (3) COUNTY CODE 145	A. FRACTURE CRITICAL DETAIL N
(4) PLACE CODE 00000	B. UNDERWATER INSPECTION N
(6) FEATURES INTERSECTED LITTLE RED RIVER RELIEF	C. OTHER SPECIAL N
(7) FACILITY CARRIED SH 367 WHITE	CONDITION
(9) LOCATION .25 M N LITTLE RED RIVER	(58) DECK 6
(11) MILEPOINT 0.730 (12) BASE HIGHWAY NETWORK 0	
(13A) LRS INVENTORY ROUTE 0000000000 (13B) SUBROUTE NUMBER 00	(59) SUPERSTRUCTURE 5 (60) SUBSTRUCTURE 6
	(61) CHANNEL & CHANNEL PROTECTION 8 (62) CULVERT N
(16) LATITUDE 35.25802 (17) LONGITUDE -91.67386	LOAD RATING AND POSTING
(98A) BORDER BRIDGE CODE	(31) DESIGN LOAD 4
PERCENT RESPONSIBILITY (99) BORDER BRIDGE STRUCT	(63) METHOD USED TO DETERMINE OPERATING RATING 1
STRUCTURE TYPE AND MATERIAL	(64) OPERATING RATING 54.0
(43) STRUCTURE TYPE, MAIN	(65) METHOD USED TO DETERMINE INVENTORY RATING 1
A) KIND OF MATERIAL/DESIGN: 3 - Steel	(66) INVENTORY RATING 32.0
B) TYPE OF DESIGN/CONSTR: 02 - Stringer/Multi-beam or Girder	(70) BRIDGE POSTING 5
(44) STRUCTURE TYPE, APPROACH SPANS	(41) STRUCTURE OPEN/POSTED/CLOSED A
A) KIND OF MATERIAL/DESIGN: 0 - Other	APPRAISAL
B) TYPE OF DESIGN/CONSTR: 00 - Other	(67) STRUCTURAL EVALUATION 5
(45) NUMBER OF SPANS IN MAIN 11 (46) NUMBER OF APPROACH 0	(68) DECK GEOMETRY 4
(107) DECK STRUCTURE TYPE 1 (108A) WEARING SURFACE 1	(69) UNDERCLEARANCES, VERTICAL & HORIZONTAL N
(108B) DECK MEMBRANE 0 (108C) DECK PROTECTION 0	(71) WATERWAY ADEQUACY 8
AGE OF SERVICE	(72) APPROACH ROADWAY ALIGNMENT 8
(27) YEAR BUILT 1948 (106) YEAR RECONSTRUCTED 0000	(36) TRAFFIC SAFETY FEATURE
(42) TYPE OF SERVICE ON 1 UNDER 5	36A) BRIDGE RAILINGS: 0
(28) LANES ON 02 UNDER 00	36B) TRANSITIONS: 0
(29) AVERAGE DAILY TRAFFIC 6800 (19) BYPASS DETOUR LENGTH 37	
(30) YEAR OF AVERAGE DAILY TRAFFIC 2014	36D) APPROACH GUARDRAIL ENDS: 0
(109) AVERAGE DAILY TRUCK TRAFFIC 1	(113) SCOUR CRITICAL BRIDGES 5
GEOMETRIC DATA	SUFFICIENCY RATING 0 STATUS 51.9
(48) LENGTH OF MAX SPAN (ft.) 36 (49) STRUCTURE LENGTH (ft.) 397	CLASSIFICATION
(50) CURB/SIDEWALK WIDTHS (ft.) LEFT 1.5 RIGHT 1.5	(112) NBIS BRIDGE LENGTH Y
(51) BRDG RDWY WIDTH CURB-TO-CURB (ft.) 27.9	(104) HIGHWAY SYSTEM OF THE INVENTORY ROUTE 0
(52) DECK WIDTH, OUT-TO-OUT (ft.) 32	(26) FUNCTIONAL CLASSIFICATION OF INVENTORY ROUTE 07
(32) APPROACH ROADWAY WIDTH (ft.) 25.9	(100) STRAHNET HIGHWAY DESIGNATION 0
(33) BRIDGE MEDIAN 0 (34) SKEW (DEG.) 0	(101) PARALLEL STRUCTURE DESIGNATION N
(35) STRUCTURE FLARED 0 (10) INV RTE, MIN VERT CLEAR (ft.) 99.99	(102) DIRECTION OF TRAFFIC 2
(47) TOTAL HORIZONTAL CLEARANCE (ft.) 30.8	(103) TEMP STRUCTURE
(53) VERTICAL CLEARANCE OVER BRIDGE ROADWAY (ft.) 99.99	(105) FEDERAL LANDS HIGHWAYS 0
(54) VERTICAL UNDER CLEARANCE (ft.) N 0	• •
(55) LATERAL UNDER CLEARANCE RIGHT (ft.) N 99.9	(110) DESIGNATED NATIONAL NETWORK 0 (20) TOLL 3
(56) MIN LATERAL UNDER CLEARANCE (ft.) 0	• •
	(21) MAINTENANCE RESPONSIBILITY 01
PROPOSED IMPROVEMENTS	(22) OM/MED 04
PROPOSED IMPROVEMENTS (75A) TYPE OF WORK PROPOSED (75B) WORK DONE BY	(22) OWNER 01
(75A) TYPE OF WORK PROPOSED (75B) WORK DONE BY	(37) HISTORICAL 5
(75A) TYPE OF WORK PROPOSED (75B) WORK DONE BY (76) LENGTH OF STRUCTURE IMPROVEMENT (ft.) 0	(37) HISTORICAL 5 NAVIGATION DATA
(75A) TYPE OF WORK PROPOSED (75B) WORK DONE BY	(37) HISTORICAL 5

(39) NAV VERT CLEARANCE (ft.) 0

(40) NAV HORIZONTAL CLEARANCE (ft.) 0

(116) MIN NAVIGATION VERT CLEARANCE, VERT LIFT BRIDGE (ft.) 0

Inspection Date: Facility Carried: SH 367 WHITE

Bridge Inspection Report

Element Inspection

12 - Reinforced Concrete Deck 1 - Ben. 12704 sq. ft. 8762 3373 569 0 Unsealed cracks to deck @ all spans. A/C overlay to Span 1 & 11. Spalls & patches along joints @ most spans. Areas of scaling & repairs to Right gutter lines @ some spans. 1080 - Delamination/Spall/Patched Area 122 97 25 1090 - Exposed Rebar 68 68 1130 - Cracking (RC and Other) 3668 3192 476 1190 - Abrasion/Wear (PSC/RC) 84 84 510 - Wearing Surfaces 1044 sq. ft. 1044 107 - Steel Open Girder/Beam 1 - Ben. 1975 ft. 1849 0 126 0 Paint peeling with some minor rust developing to girders @ random areas @ all spans. Rust with section loss to webs below paving haunch, diaphragm			<u> </u>	<u> </u>		1 .	1 .				
Unsealed cracks to deck @ all spans. A/C overlay to Span 1 & 11. Spalls & patches along joints @ most spans. Areas of scaling & repairs to Right gutter lines @ some spans. 1080 - Delamination/Spall/Patched Area 1090 - Exposed Rebar 68 1130 - Cracking (RC and Other) 3668 11190 - Abrasion/Wear (PSC/RC) 84 107 - Steel Open Girder/Beam 108 - Paint peeling with some minor rust developing to girders @ random areas @ all spans. Rust with section loss to webs below paving haunch, diaphragm connections &/or bottom of webs to ends of girders @ all spans. Rust with section loss to webs below paving haunch, diaphragm connections &/or bottom of webs to ends of girders @ all spans. (Ends of girders have been cleaned & painted @ most spans, but section loss, holes & some rust still exist.) Span 2 - Girder 3 has holes in web. Span 3 - Girder 4 has large hole in web below paving haunch. Span 6 - Girder 2 & 4 has holes in web. Span 9 - Girder 2 has holes in web. Span 9 - Girder 2 has holes in web. Span 10 - Girder 2 has holes in web. Span 10 - Girder 3 has holes in web. Span 10 - Girder 3 has holes in web. Span 6 - Girder 2 has holes in web. Span 6 - Girder 2 has holes in web. Span 10 - Girder 3 has holes in web. Span 10 - Girder 3 has holes in web. Span 6 - Girder 2 has holes in web. Span 6 - Girder 3 has holes in web. Span 6 - Girder 3 has holes in web. Span 6 - Girder 3 has holes in web. Span 6 - Girder 3 has holes in web. Span 6 - Girder 3 has holes in web. Span 6 - Girder 3 has holes in web. Span 6 - Girder 3 has holes in web. Span 6 - Girder 3 has holes in web. Span 6 - Girder 3 has holes in web. Span 6 - Girder 3 has holes in web. Span 6 - Girder 3 has holes in web. Span 6 - Girder 3 has holes in web. Span 6 - Girder 3 has holes in web. Span 10 - Girder 3 has holes in web. Span 10 - Girder 3 has holes in web. Span 10 - Girder 3 has holes in web. Span 10 - Girde		Environment	Total Quantity	Units	Condition State 1	Condition State 2					
A/C overlay to Span 1 & 11. Spalls & patches along joints @ most spans. Areas of scaling & repairs to Right gutter lines @ some spans. 1080 - Delamination/Spall/Patched Area 1090 - Exposed Rebar 1090 - Exposed Rebar 1090 - Exposed Rebar 1090 - Carcking (RC and Other) 1090 - Abrasion/Wear (PSC/RC) 1090 - Steel Open Girder/Beam 1091 - Steel Open Girder/Beam 1091 - Steel Open Girder/Beam 1091 - Steel Open Girder/Beam 1092 - Steel Open Girder/Beam 1093 - Steel Open Girder/Beam 1094 - Steel Open Girder/Beam 1094 - Steel Open Girder/Beam 1095 - Steel Open Girder Seam 1095 - Steel Open Girder/Beam 1096 - Steel Open Girder Seam 1097 - Steel Open Girder Seam 1098 - Seam - Se	12 - Reinforced Concrete Deck	1- Ben.	12704	sq. ft.	8762	3373	569	0			
1090 - Exposed Rebar 1130 - Cracking (RC and Other) 3668 3192 476		Unsealed cracks to deck @ all spans. A/C overlay to Span 1 & 11. Spalls & patches along joints @ most spans.									
1130 - Cracking (RC and Other) 3668 3192 476 1190 - Abrasion/Wear (PSC/RC) 84 84 84 107 - Steel Open Girder/Beam 1 · Ben. 1975 ft. 1849 0 126 0 Paint peeling with some minor rust developing to girders @ random areas @ all spans. Rust with section loss to webs below paving haunch, diaphragm connections &/or bottom of webs to ends of girders @ all spans. (Ends of girders have been cleaned & painted @ most spans, but section loss, holes & some rust still exist.) Span 2 - Girder 3 has holes in web. Span 3 - Girder 4 has large hole in web below paving haunch. Span 3 - Girder 2 & 4 has holes in web. Span 4 - Girder 2 has holes in web. Span 9 - Girder 3 has holes in web. Span 10 - Girder 3 has holes in web. Span 10 - Girder 3 has holes in web. Span 10 - Girder 3 has holes in web. Span 10 - Girder 3 has holes in web. Span 10 - Girder 3 has holes in web. Span 10 - Girder 3 has holes in web. Span 10 - Girder 5 has section loss & is crushing @ ends. SEE FORM III 1000 - Corrosion 104	1080 - Delamination/Spall/Patched Area		122			97	25				
1190 - Abrasion/Wear (PSC/RC) 84	1090 - Exposed Rebar		68				68				
1.5en. 1044 sq. ft. 1044 o 126 o 126 o 126 o 126 o 126 o 126 o Paint peeling with some minor rust developing to girders @ random areas @ all spans. Rust with section loss to webs below paving haunch, diaphragm connections &/or bottom of webs to ends of girders @ all spans. (Ends of girders have been cleaned & painted @ most spans, but section loss, holes & some rust still exist.)	1130 - Cracking (RC and Other)		3668			3192	476				
1-Ben. 1975 ft. 1849 0 126 0 Paint peeling with some minor rust developing to girders @ random areas @ all spans. Rust with section loss to webs below paving haunch, diaphragm connections &/or bottom of webs to ends of girders @ all spans. (Ends of girders have been cleaned & painted @ most spans, but section loss, holes & some rust still exist.) Span 2 - Girder 3 has holes in web. Span 3 - Girder 4 has large hole in web below paving haunch. Span 6 - Girder 2 & 4 has holes in web below paving haunch. Span 8 - Girder 3 & 4 has holes in web. Span 9 - Girder 2 has holes in web. Span 10 - Girder 3 has holes in web. Span 10 - Girder 3 has holes in web. Span 10 - Girder 3 has holes in web below paving haunch. Spans 6 - His Girder 5 has section loss & is crushing @ ends. SEE FORM III 1000 - Corrosion 104 104 104 104 104 104 104 104 104 104	1190 - Abrasion/Wear (PSC/RC)		84			84					
Paint peeling with some minor rust developing to girders @ random areas @ all spans. Rust with section loss to webs below paving haunch, diaphragm connections &/or bottom of webs to ends of girders @ all spans. (Ends of girders have been cleaned & painted @ most spans, but section loss, holes & some rust still exist.) Span 2 - Girder 3 has holes in web. Span 3 - Girder 4 has large hole in web below paving haunch. Span 6 - Girder 2 & 4 has holes in web below paving haunch. Span 8 - Girder 2 & 4 has holes in web below paving haunch. Span 9 - Girder 2 has holes in web. Span 10 - Girder 3 has holes in web. Span 10 - Girder 3 has holes in web below paving haunch. Span 6 -11 Girder 5 has section loss & is crushing @ ends. SEE FORM III 1000 - Corrosion 1000 - Distortion 22 2 22 515 - Steel Protective Coating 11850 sq. ft. 11258 0 592 205 - Reinforced Concrete Column 1 - Ben. 56 each 0 54 2 0 Bent 2 - Pile 5 has spall with rebar exposed. Bent 6 - Pile 1 has vertical cracks. Abrasion to all conc. columns 1090 - Exposed Rebar 1130 - Cracking (RC and Other) 1190 - Abrasion/Wear (PSC/RC) 1- Ben. 84 ft. 41 0 34 9 Abutment 1 - Ben. 84 ft. 41 0 34 9 Abutment 1 - Heavy spalling to Left & Right wings. Abutment 1 - Heavy spalling to Left & Right wings. Abutment 1 - Heavy spalling to Left & Right wings. Abutment 1 - Heavy spalling to Left & Right wings.	510 - Wearing Surfaces		1044	sq. ft.	1044						
areas @ all spans. Rust with section loss to webs below paving haunch, diaphragm connections &/or bottom of webs to ends of girders @ all spans. (Ends of girders have been cleaned & painted @ most spans, but section loss, holes & some rust still exist.) Span 2 - Girder 3 has holes in web. Span 3 - Girder 4 has large hole in web below paving haunch. Span 6 - Girder 2 & 4 has holes in web. Span 8 - Girder 2 & 4 has holes in web. Span 9 - Girder 2 has holes in web. Span 9 - Girder 2 has holes in web. Span 9 - Girder 2 has holes in web. Span 9 - Girder 2 has holes in web. Span 9 - Girder 2 has holes in web. Span 9 - Girder 2 has holes in web. Span 9 - Girder 3 has holes in web. Span 9 - Girder 3 has holes in web. Span 10 - Girder 3 has holes in web. Span 6 - 11 Girder 5 has section loss & is crushing @ ends. SEE FORM III 1000 - Corrosion 104 1900 - Distortion 22 22 515 - Steel Protective Coating 11850 sq. ft. 11258 0 592 0 3440 - Effectiveness (Steel Protective Coatings) 592 205 - Reinforced Concrete Column 1- Ben. 56 each 0 54 2 0 Bent 2 - Pile 5 has spall with rebar exposed. Bent 6 - Pile 1 has vertical cracks. Abrasion to all conc. columns 1090 - Exposed Rebar 1130 - Cracking (RC and Other) 1 1 1190 - Abrasion/Wear (PSC/RC) 54 54 215 - Reinforced Concrete Abutment Abutment 1 - Ben. 84 ft. 41 0 34 9 Abutment 1 - Bens. 84 ft. 41 0 34 9 Abutment 1 - Heavy spalling to Left & Right wings. Abutment 1 - Heavy spalling to Left & Right wings. Abutment 1 - Heavy spalling to Left & Right wings. Abutment 1 - Heavy spalling to Left & Right wings.	107 - Steel Open Girder/Beam	1- Ben.	1975	ft.	1849	0	126	0			
1900 - Distortion 22	1000 - Corrosion	Rust with section loss to webs below paving haunch, diaphragm connections &/or bottom of webs to ends of girders @ all spans. (Ends of girders have been cleaned & painted @ most spans, but section loss, holes & some rust still exist.) Span 2 - Girder 3 has holes in web. Span 3 - Girder 4 has large hole in web below paving haunch. Span 6 - Girder 2 & 4 has holes in web below paving haunch. Span 8 - Girder 3 & 4 has holes in web. Span 9 - Girder 2 has holes in web. Span 10 - Girder 3 has holes in web below paving haunch. Spans 6 -11 Girder 5 has section loss & is crushing @ ends. SEE FORM III									
11850 sq. ft. 11258 0 592 0		-	22								
3440 - Effectiveness (Steel Protective Coatings) 205 - Reinforced Concrete Column 1- Ben. 56 each 0 54 2 0 Bent 2 - Pile 5 has spall with rebar exposed. Bent 6 - Pile 1 has vertical cracks. Abrasion to all conc. columns 1090 - Exposed Rebar 1 1 1130 - Cracking (RC and Other) 1 1 1190 - Abrasion/Wear (PSC/RC) 215 - Reinforced Concrete Abutment Abutment 1 & 2 have rotated in the past. Repairs have stabilized rotation, no visible movement @ this time. Abutment 1 - Heavy spalling to Left & Right wings. Abutment 2 - Large spalls with rebar exposed to Abutment. Horizontal crack to abutment.			11850	sq. ft.	11258	0	592	0			
205 - Reinforced Concrete Column 1- Ben. 56 each 0 54 2 0 Bent 2 - Pile 5 has spall with rebar exposed. Bent 6 - Pile 1 has vertical cracks. Abrasion to all conc. columns 1090 - Exposed Rebar 1 1 1 1130 - Cracking (RC and Other) 1 1 1190 - Abrasion/Wear (PSC/RC) 54 54 215 - Reinforced Concrete Abutment 1- Ben. 84 ft. 41 0 34 9 Abutment 1 & 2 have rotated in the past. Repairs have stabilized rotation, no visible movement @ this time. Abutment 1 - Heavy spalling to Left & Right wings. Abutment 2 - Large spalls with rebar exposed to Abutment. Horizontal crack to abutment.		1	592				592				
Bent 6 - Pile 1 has vertical cracks. Abrasion to all conc. columns 1090 - Exposed Rebar 1 1 1 1130 - Cracking (RC and Other) 1 1 1 1190 - Abrasion/Wear (PSC/RC) 54 54 215 - Reinforced Concrete Abutment 1 - Ben. 84 ft. 41 0 34 9 Abutment 1 & 2 have rotated in the past. Repairs have stabilized rotation, no visible movement @ this time. Abutment 1 - Heavy spalling to Left & Right wings. Abutment 2 - Large spalls with rebar exposed to Abutment. Horizontal crack to abutment.	,	+	56	each	0	54	2	0			
1130 - Cracking (RC and Other) 1190 - Abrasion/Wear (PSC/RC) 215 - Reinforced Concrete Abutment 1 - Ben. Abutment 1 & 2 have rotated in the past. Repairs have stabilized rotation, no visible movement @ this time. Abutment 1 - Heavy spalling to Left & Right wings. Abutment 2 - Large spalls with rebar exposed to Abutment. Horizontal crack to abutment.		Bent 2 - Pile 5 has spall with rebar exposed. Bent 6 - Pile 1 has vertical cracks.									
1190 - Abrasion/Wear (PSC/RC) 215 - Reinforced Concrete Abutment 1- Ben. 84 ft. 41 0 34 9 Abutment 1 & 2 have rotated in the past. Repairs have stabilized rotation, no visible movement @ this time. Abutment 1 - Heavy spalling to Left & Right wings. Abutment 2 - Large spalls with rebar exposed to Abutment. Horizontal crack to abutment.	1090 - Exposed Rebar	•	1				1				
215 - Reinforced Concrete Abutment 1- Ben. 84 ft. 41 0 34 9 Abutment 1 & 2 have rotated in the past. Repairs have stabilized rotation, no visible movement @ this time. Abutment 1 - Heavy spalling to Left & Right wings. Abutment 2 - Large spalls with rebar exposed to Abutment. Horizontal crack to abutment.	1130 - Cracking (RC and Other)		1				1				
Abutment 1 & 2 have rotated in the past. Repairs have stabilized rotation, no visible movement @ this time. Abutment 1 - Heavy spalling to Left & Right wings. Abutment 2 - Large spalls with rebar exposed to Abutment. Horizontal crack to abutment.	1190 - Abrasion/Wear (PSC/RC)		54			54					
Repairs have stabilized rotation, no visible movement @ this time. Abutment 1 - Heavy spalling to Left & Right wings. Abutment 2 - Large spalls with rebar exposed to Abutment. Horizontal crack to abutment.	215 - Reinforced Concrete Abutment	1- Ben.	84	ft.	41	0	34	9			
1080 - Delamination/Spall/Patched Area 9 9		Repairs have stabilized rotation, no visible movement @ this time. Abutment 1 - Heavy spalling to Left & Right wings. Abutment 2 - Large spalls with rebar exposed to Abutment.									
	1080 - Delamination/Spall/Patched Area		9					9			

Inspection Date: Facility Carried: SH 367 WHITE

Bridge Inspection Report

Element Inspection

1090 - Exposed Rebar		4				4			
1120 - Efflorescence/Rust Staining		30				30			
234 - Reinforced Concrete Pier Cap	1- Ben.	290	ft.	282	1	7	0		
	Bent 2 - Spall with 1' rebar exposed near Pile 5 Bent 4 - Spall, cracks to left end of cap. Cracks & delam. to Right end of cap. Spall top of cap @ bearing 3 Bent 6 - Cracks & delam. near Pile 1 Bent 10 - Horiz. crack to bottom of cap back & ahd. of Pile 3.								
1080 - Delamination/Spall/Patched Area		2			1	1			
1090 - Exposed Rebar		2				2			
1120 - Efflorescence/Rust Staining		4				4			
305 - Assembly Joint without Seal	1- Ben.	372	ft.	0		372			
	All joints are closed from Abutments rotating ahead & back.								
311 - Movable Bearing	1- Ben.	55	each	0	0	55	0		
	All moveable bearings have rotated ahead/back. Section loss to several anchor bolts with some bent or missing @: Bent 2 - Girders 2, 3, 5. Bent 4 - Girders 1, 2, 3. Bent 5 - Girders 1, 2, 3, 4, 5. Bent 6 - Girder 4. Bent 7 - Girder 3, 4. Bent 9 - Girder 1								
1000 - Corrosion		55				55			
515 - Steel Protective Coating		110	sq. ft.	0	0	110	0		
3440 - Effectiveness (Steel Protective Coatings)		110				110			
313 - Fixed Bearing	1- Ben.	55	each	0	55	0	0		
	Bearings have been cleaned & painted, but minor section loss still exist.								
1000 - Corrosion		55			55				
515 - Steel Protective Coating		110	sq. ft.	0	110	0	0		
3440 - Effectiveness (Steel Protective Coatings)		110			110				
331 - Reinforced Concrete Bridge Railing	1- Ben.	1588	ft.	1571	0	17	0		
	Span 2 - Spall with rebar exposed to 6th concrete post on Left. Span 4 - 1st & 2nd concrete post on Left is broken with top & bottom rail spalled/cracked. Span 7 - 1st concrete post on Left cracked/spalled @ top. Span 9 - 2nd concrete post on Left cracked/spalled @ top.								
1080 - Delamination/Spall/Patched Area		15				15			
1090 - Exposed Rebar	•	2				2			

Inspection Date: Facility Carried: SH 367 WHITE

Bridge Inspection Report

Pictures

Inspection Date: Facility Carried: SH 367 WHITE

Bridge Inspection Report

Sketches

Inspection Date: Facility Carried: SH 367 WHITE

Bridge Inspection Report

Maintenance Needs

Date Reported: 11/08/2016

Priority: C - Important

Work Code:

Deficiency Description:

Span 4 - 1st and 2nd concrete post of left is broken & lower concrete rail is cracked, top rail is off post on one end.

Work Description:

Date Repairs Completed:

Maintenance Comments:

Stage: Open



PHOTO 1 Description

1st and 2nd concrete post of left at Span 4 is broken & lower concrete rail is cracked, top rail is off post on one end.

Stage: Open



PHOTO 2 Description

1st and 2nd concrete post of left at Span 4 is broken & lower concrete rail is cracked, top rail is off post on one end.

Inspection Date: Facility Carried: SH 367 WHITE

Bridge Inspection Report

Maintenance Needs

Date Reported: 11/08/2016

Priority: C - Important

Work Code:

Deficiency Description:

Abutment 1 - Heavy spalling to left & right wings.

Abutment 2 - Right Wing & Left Wing is cracked and spalled. Left wing has rotated.

Work Description:

Date Repairs Completed:

Maintenance Comments:

Stage: Open



PHOTO 1 Description

Typical of Right & Left Wings at Abutment 2 cracked and spalled. (Right at Abt. 2)

Stage: Open



PHOTO 2

Description

Typical of heavy spalling to Left & Right wings at Abutments 1 & 2. (Left Wing at Abt. 1.)

Inspection Date: Facility Carried: SH 367 WHITE

Bridge Inspection Report

Maintenance Needs

Date Reported: 11/20/2012 12:00:00 AM

Priority: D - Routine

Work Code:

Deficiency Description:

Unsealed cracks to deck at all spans.

Spalling along sliding plate joints at Bents 1 - 4 & 6 - 10.

Spalling & epoxy patch failures in right gutter line at Spans 2, 5, 7, & 10.

Work Description:

Date Repairs Completed:

Maintenance Comments:



PHOTO 1 D

Description

Spalling along sliding plate joints at Bents 1 - 4 & 6 -10.

Stage: Assigned



PHOTO 2

Description

Spalling & epoxy patch failures in right gutter line Spans 2, 5, 7, & 10.

Inspection Date: Facility Carried: SH 367 WHITE

Bridge Inspection Report

Maintenance Needs



PHOTO 3 Description

Typical of unsealed cracks to deck at all spans.

Inspection Date: Facility Carried: SH 367 WHITE

Bridge Inspection Report

Maintenance Needs

Date Reported: 11/20/2012 12:00:00 AM

Priority: C - Important

Work Code:

Deficiency Description:

Section loss to webs below paving haunch, diaphragm connections &/or bottom flanges at ends of girders with holes in webs below paving haunch to:

Span 2 - Girder 3.

Span 3 - Girder 4.

Span 6 - Girders 2 & 4.

Span 8 - Girders 3 & 4.

Span 9 - Girder 2.

Span 10 - Girder 3.

Out of plane bending to:

Span 2 - Girder 1 at beginning of span.

Span 6 - Girder 5 at beginning of span.

Span 7 - Girder 5 at beginning & end of span.

Span 8 - Girder 5 at beginning of span.

Span 9 - Girder 5 at beginning & end of span.

Span 10 - Girder 5 at beginning & end of span.

Work Description:

Date Repairs Completed:

Maintenance Comments:

Stage: Assigned



PHOTO 1 Description

Span 3 - Girder 4 has section loss & hole to webs below paving haunch. Typical of several areas. See Form III

Inspection Date: Facility Carried: SH 367 WHITE

Bridge Inspection Report

Maintenance Needs



PHOTO 2 Description Tyl

Typical of Out of plane bending to girders. See Form III

Inspection Date: Facility Carried: SH 367 WHITE

Bridge Inspection Report

Maintenance Needs

Date Reported: 11/20/2012 12:00:00 AM

Priority: D - Routine

Work Code:

Deficiency Description:

Spall with 1' rebar exposed to Pile 5 at Bent 2.

Vertical cracks with delaminated area to top of Pile 1 at Bent 6.

Work Description:

Date Repairs Completed:

Maintenance Comments:



PHOTO 1

Description

Spall with 1' rebar exposed to Pile 5 at Bent 2.

Stage: Assigned



PHOTO 2

Description

Vertical cracks with delaminated area to top of Pile 1 at Bent 6.

Inspection Date: Facility Carried: SH 367 WHITE

Bridge Inspection Report

Maintenance Needs

Date Reported: 11/20/2012 12:00:00 AM

Priority: D - Routine

Work Code:

Deficiency Description:

Spalls with rebar exposed to left & right overhangs at all spans.

Work Description:

Date Repairs Completed:

Maintenance Comments:



PHOTO 1

Description

Typical of spalls with rebar exposed to left & right overhangs at all spans. (Bent 2)

Inspection Date: Facility Carried: SH 367 WHITE

Bridge Inspection Report

Maintenance Needs

Date Reported: 11/20/2012 12:00:00 AM

Priority: B - Pressing; 6 month completion goal

Work Code:

Deficiency Description:

Heavy section loss to all moveable bearings.

Section loss to several anchor bolts with some bent or missing.

Work Description:

Date Repairs Completed:

Maintenance Comments:

Stage: Assigned



PHOTO 1 Description

Heavy section loss to all moveable bearings
Section loss to several anchor bolts and nuts with some bent or missing.






PHOTO 2

Description

Heavy section loss to all moveable bearings. (EOS 7)





A. TRAFERO S.

