

## INTEROFFICE MEMORANDUM

**DATE:** September 24, 1986

**TO:** BRIDGE DESIGN PERSONNEL  
**FROM:** Veral Pinkerton, Bridge Engineer  
**SUBJECT:** Cracked Concrete

From time to time we are asked to review, comment, and make recommendations regarding concrete that has cracked for various reasons.

It will be our general policy that any cracks, at any location, which are large enough to be of concern (approximately 0.01" in width) should be completely filled by pressure grouting with an epoxy.