



Parker Thru Truss

(5)

- * In-Service NR Parker Thru Truss (3)
- Demolished NR and RP Parker Thru Truss (3)
- ▣ Preserved Parker Thru Truss (0)
- ◉ Reserve Pool Parker Thru Truss (0)
- Evaluation Parker Thru Truss (2)



Evaluation Bridges Properties	
General Attributes	
Name	Value
Bridge_Number	01412
Type	310
HAER_Number	
county_name	Clark
District	7
Route	51
Section	02
Date_Built	1933
SHPO_Number	
Log_Mile	0.38
Photo1	\\sql2\qis\Environmental\HB_Photos\01412\01412.pdf
Name	Ouachita River
Description	Parker Thru Truss
Topographic_Map	Arkadelphia
Programmed	No
HB_Inventory_Date	
Water_Crossing	Ouachita River
Demolished	No
In_Service	Yes
HAER	
Nat_Reg_Form	
Pool_Reserve	No
HB_Demolish	
Marketing_Letter	
FHWA_4f	
SHPO_MOA	
Evaluation	True
Unique_Attributes	
Spans	1
Main_Span_Length	202
Main_Span_Width	24
Vertical	15.11
Total_Length	503
Photographed	True
Field_Condition	excellent

EVALUATION BRIDGE #01412
STATE HIGHWAYS 7 & 51
CLARK COUNTY
PARKER THRU TRUSS
CONDITION – EXCELLENT
BUILDER – LUTEN BRIDGE COMPANY



Evaluation Bridges to be Photographed Properties	
General Attributes	
Name	Value
Bridge_Number	03139
Type	310
HAER_Number	
county_name	Conway
District	8
Route	124
Section	03
Date_Built	1957
SHPO_Number	
Log_Mile	7.43
Photo1	\\sql2\gis\Environmental\HB Photos\03139\03139.pdf
Name	
Description	Parker Thru Truss
Topographic_Map	Hattiville
Programmed	No
HB_Inventory_Date	
Water_Crossing	Point Remove Creek
Demolished	No
In_Service	Yes
HAER	
Nat_Reg_Form	
Pool_Reserve	No
HB_Demolish	
Marketing_Letter	
FHWA_4f	
SHPO_MOA	
Evaluation	True
Unique_Attributes	approach - parker pony truss
Spans	2
Main_Span_Length	132
Main_Span_Width	21.1
Vertical	15.4
Total_Length	256
Photographed	True
Field_Condition	good

EVALUATION BRIDGE #03139
STATE HIGHWAY 124
CONWAY COUNTY
PARKER THRU TRUSS
CONDITION – GOOD
BUILDER – FORSGREN BROTHERS, FORT SMITH, AR